- 1. Replace defective request-to-exit motion on front lobby entrance door with new request-to-exit device.
- Install additional wire for all devices at the front lobby entrance door for possible relocation at a later date. Additional wire may be coiled and stored above the ceiling in the lobby area.
- 3. Vendor will remove existing request-to-exit buttons on front lobby entrance door and rear entrance door and replace with blank cover plate
- All wire inside of walls connected to existing devices being replaced as a part of this
  project must be removed up to the ceiling. Wire should be cut above the ceiling and
  disposed of properly.
- Replace any existing maglocks on access controlled doors identified in this proposal with electric door strikes.
- 6. Vendor will install a UL rated 24 VAC 16 channel power supply for cctv system. The power supply shall be an Altronix ALTV2416-ULX or its equivalent.
- 7. The DVR shall be a 16 channel DVR with 1TB of storage and rack-mountable.
- 8. DVR may use MPEG-4 or H.264 video compression format.
- HID reader on front lobby entrance door is to be moved and installed at access door for help desk room.
- 10. Aiphone door station for front lobby entrance shall have an integrated HID reader and access control keypad. Door station model shall be JF-DVF-HID or equivalent. Keypad reader shall be AC-10S which integrates with the door station to make one unit.
- 11. Aiphone master station shall be JF-2MED or equivalent. Aiphone sub-station shall be JF-2HD or equivalent
- 12. Vendor is to provide 8 hours of training for all installed systems as a part of this proposal.
- 13. Vendor will include 1 year of Technical support on access control & cctv systems installed. Technical support may be online, telephone or live.
- 14. Vendor shall include 3 years of monitoring of the BA system by a UL rated central monitoring station as a part of its proposal.
- 15. Installation price shall be all inclusive including labor, wire, demo, training and monitoring.
- 16. An additional camera is to be added and should have the same specifications as the three Sony cameras currently in the bid.
- 17. An additional HID reader will be needed and installed on new door due to remodel of Hopper St. lobby.